



TEC[®]**INSTALLATION INSTRUCTIONS
5000 WATER COOLED TIG SPOT GUN****600-0W PCA - ADAPTER
FOR STUD MACHINE**

- Turn off power supply. Mount the power cable adapter to electrode (torch) stud on the power supply.
- Screw the brass nut (power cable) and brass nut (water return hose) into adapter. Connect other end of hose to water return (water in) side of water cooler. Note Left Hand - "LH" threads. Tighten only snug. Do not over tighten.
- Connect gas to machine gas output, solenoid controlled.
- Connect adapter 600-0W to machine negative.



COPYRIGHT 2005 - 2018 TEC WELDING PRODUCTS, INC.